

SPEC SHEET + MEASUREMENTS



Gildan® Ultra Cotton® 100% US Cotton T-Shirt. 2000

PRODUCT MEASUREMENTS

	S	M	L	XL	2XL	3XL	4XL	5XL
Body Length at Back	28	29	30	31	32	33	34	35
Chest	18	20	22	24	26	28	30	32
Sleeve Length	16 1/2	18	19 1/2	21	22 1/2	24	25 1/4	26 1/2

Body Length at Back: Measured from high point shoulder to finished hem at back.


Chest: Measured across the chest one inch below armhole when laid flat.

Sleeve Length: Start at center of neck and measure down shoulder, down sleeve to hem.

SIZE CHARTS

	S	M	L	XL	2XL	3XL	4XL	5XL
Chest	34-36	38-40	42-44	46-48	50-52	54-56	58-60	62-64

HOW TO MEASURE



CHEST

Measure under the arm and around the fullest part of the chest with arms down, keeping tape horizontal.